Name: Hinderclay Village Hall and Playing Field

Assessment carried out by: R M Shreeves

Date of next review: January 2026 Date assessment was carried out: 8<sup>th</sup> January 2025

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
Slips Trips and Falls	Committee members, Parishioners, Any visitor, Contractors	Spillages to be cleared up immediately. All work areas to be kept tidy. Signage to be used as necessary. Floor, recreation field and car park surfaces to be kept clear of debris and in good condition. Monthly inspections to be carried out.	Continued monitoring when hall is in use.	Committee or appropriate hirers or contractors.	Ongoing	
Access and Egress	Committee members, Parishioners, Any visitor, Contractors	Nonslip mats at the front and rear doors. Notices warning of exiting onto car park.	Continued monitoring	Committee or appropriate hirers or contractors	Ongoing	

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
Car Park	Committee members, Parishioners, Any visitor, Contractors	The car park is adjacent to a crossroads, boundary hedges are kept low so that vision and hearing is not obstructed. The car park is for hall users and visitors only and there is no general right of way or access for vehicles.  Access and egress points are wide and the one closest to the crossroads is clearly marked as 'NO EXIT'. There is ample room for emergency vehicles to enter and exit.  Contractors are made aware that members of the public use the car park.	Continued monitoring	Committee or appropriate hirers or contractors	Ongoing	
Hazardous substances	Committee members, Parishioners, Any visitor, Contractors	Only to be used by competent Committee members or contractors. To be stored in a designated cupboard. Contractors to provide C.O.S.H.H risk assessments for each product used.	Hazardous substance register to be maintained and kept.	Committee and contractor.	Ongoing	

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
Electricity (including switch room and Battery Room)	Committee members, Parishioners, Any visitor, Contractors	Regular inspections of electrical fittings by qualified electrical contractor. All mains electrical devices brought onto premises to be PAT tested. Electrical Warning signs are displayed.	Inspections	Electrical Contractor and Committee	Ongoing	Annual
Stored Equipment	Committee members, Parishioners, Any visitor, Contractors	Stored equipment to be supervised by a committee member, in a designated storage area.		Committee or appropriate hirers or contractors	Ongoing	
Manual Handling	Committee members, Parishioners, Any visitor, Contractors	Manual handling to be carried out by competent person, or persons, at their own risk.	Wearing of correct PPE.(suitable gloves)	Committee or appropriate hirers or contractors	Ongoing	

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
Asbestos	Committee members, Parishioners, Any visitor, Contractors	Artex is on the ceiling in the hall. Tests have been carried out on the Artex and a record is kept. Competent Contractors and anyone working on the ceiling must wear appropriate PPE, cordon off work areas and use appropriate signage to warn of the potential hazard.	After any works on the Artex have taken place, the hall must be cleaned and air samples taken for asbestos particles.	Committee. Qualified contractor.	After any works involving the ceiling which could cause damage to the Artex.	
Fire	Committee members, Parishioners, Any visitor, Contractors	The hall is equipped with a fully maintained fire extinguishers and fire alarm The emergency escape doors are clearly marked. There are permanently lit emergency lights which remain on if power is cut. Extinguishers are inspected annually. Emergency lights and fire alarm are inspected by a qualified contractor 6 monthly. Certificate issued and recorded.	Continued monitoring.	Committee. Qualified Contractor	Ongoing	Annually and 6 monthly

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
Working at height	Committee members, Parishioners, Any visitor, Contractors	Appropriate equipment to be used if working at height. Signage and barriers to be used as necessary.		Committee Contractor	During works process.	
Playing Field and Equipment	Committee members, Parishioners, Any visitor, Contractors	Goal Posts and Netball/Basketball hoops are regularly inspected for damage, the grassed area is routinely cut and the gates and picnic table are inspected.	Continued inspection's	Committee Contractor	Ongoing	
Other	Committee members, Parishioners, Any visitor, Contractors	Hirers/Contractor's undertake full responsibility for their activities and if required should provide their own risk assessments for any hazardous activities or sports.		Hirers/Contractor's	During hire/Work period.	